
Academic 1 - Fix Curtain Wall Leaks (Project PN 22-175251) A01 2023-075M22


University of Colorado Denver-Anschutz Medical Campus 12631 East 17th Avenue Aurora, Colorado 80045

MARTIN/MARTIN PROJECT NO. 20.0814.S.04 ISSUE DATE:May 1, 2023

AERIAL PHOTO



VICINITY MAP



CONSULTANT



12499 WEST COLFAX AVENUE, LAKEWOOD, COLORADO 80215 MAIN 303.431.6100 MARTINMARTIN.COM

CONTACT: Dave Villella 303.888.2076 dvillella@martinmartin.com

OWNER'S REPRESENTATIVE


Andy Madsen - Project Manager
University of Colorado Denver

CONTACT: (303) 880-7569

E-MAIL:andy.madsen@cuanschutz.edu

DRAWING INDEX

DIAMINO INDEX		
SHEET NUMBER	SHEET NAME	
S0.01	NOTES	
S0.02	SPECS	
S1.10	PLANS	
S2.01	ELEVATIONS	
S2.02	ELEVATIONS	
S2.03	ELEVATIONS	
S2.04	ELEVATIONS	
S2.05	ELEVATION DETAILS	
S3 00	DETAILS.	



6. OSHA STANDARDS:

COMPLY WITH ALL OSHA REQUIREMENTS.

NECESSARY TO COMPLY WITH OSHA.

6A. THE SYSTEM IS DESIGNED TO FUNCTION AS A UNIT UPON COMPLETION. NOTHING SHOWN ON THE STRUCTURAL DRAWINGS SHALL BE CONSTRUED AS ELIMINATING THE NEED FOR THE CONTRACTOR TO

WINDOW DAMAGE

WHEN CONTRACTOR DISCOVERS A BROKEN WINDOW FRAME OR DAMAGES A WINDOW FRAME

DURING CONSTRUCTION - CONTACT MARTIN/MARTIN FOR REVISED WINDOW DETAILS

P. BROKEN GLASS - CONTACT MARTIN/MARTIN FOR REPLACEMENT REQUIREMENTS

6B. WHERE THE DRAWINGS APPEAR TO CONFLICT WITH OSHA REQUIREMENTS, THE DRAWINGS REPRESENT FINAL CONDITIONS ONLY. THE CONTRACTOR SHALL ADD ALL ERECTION FRAMING

ACADEMIC 1 - FIX

SINGUISION STATES AND STATE Anschutz Medical Campus

12631 East 17th Avenue
Aurora, Colorado 80045

5M2

9

0

A0

0 ~

MARTIN/MARTIN

NO. ISSUE DATE


PROJECT NO: DATE:

TE: 08/27/2021 © MARTIN/MARTIN 2020

20.0814.S.04

SHEET TITLE:
NOTES

SHEET NUMBER:



MARTIN/MARTIN
CONSULTING ENGINEERS 12499 WEST COLFAX AVENUE, LAKEWOOD, COLORADO 80215 MAIN 303.431.6100 MARTINMARTIN.COM

> 1 - FIX CURTAIN WALL LEAKS PN 22-175251) A01 2023-075M22 ACADEMIC (PROJECT F

REVISIONS NO. ISSUE DATE

20.0814.S.04

08/27/2021


PROJECT NO:

© MARTIN/MARTIN 2020 SHEET TITLE: PLANS

SHEET NUMBER: S1.10

9 8 1.7 (1.4) 8'-5" — 32'-0" 32'-0" 32'-0" 32'-0" 32'-0" 32'-0" В (B.4) <u>C</u> 220 VOLT OUTLET TYPICAL AT EACH CORNER S2.04 1 1 S2.02 E 8 6 1.3 1 ROOF PLAN
1/16" = 1'-0"

- NOTE:
 1. FIELD VERIFY EXISTING DIMENSIONS PRIOR TO FABRICATION AND CONSTRUCTION.
 2. COORDINATE WORK AREAS AND ACCESS WITH OWNER.
 3. CONTRACTOR TO REPAIR RESULTING DAMAGE ASSOCIATED WITH REPAIRS INCLUDING LANDSCAPING, ADJACENT WALLS AND ROOF



1 - FIX CURTAIN WALL LEAKS PN 22-175251) A01 2023-075M22 ACADEMIC (PROJECT F REVISIONS ISSUE


DATE

PROJECT NO:

20.0814.S.04 08/27/2021 © MARTIN/MARTIN 2020

ELEVATIONS

SHEET NUMBER: S2.01



SOUTH ELEVATION

1. FIELD VERIFY EXISTING DIMENSIONS PRIOR TO FABRICATION AND CONSTRUCTION.

COORDINATE WORK AREAS AND ACCESS WITH OWNER.
 CONTRACTOR TO REPAIR RESULTING DAMAGE ASSOCIATED WITH REPAIRS INCLUDING LANDSCAPING, ADJACENT WALLS AND ROOF

1 - FIX CURTAIN WALL LEAKS PN 22-175251) A01 2023-075M22 ACADEMIC (PROJECT F REVISIONS NO. ISSUE DATE

S2.02


© MARTIN/MARTIN 2020

ELEVATIONS

20.0814.S.04

08/27/2021

PROJECT NO:



(B.4) 1 2 3 4 5 6 11 LEVELS 1- ROOF T.O. PARAPET 238'-0" TYPICAL AT PUNCHED OPENINGS IN BRICK T.O. PARAPET 230'-2-1/2" + T.O. PARAPET 214'-4" + LEVEL EIGHT 193'-4" LEVEL SEVEN
180'-0" + LEVEL SIX 166'-8" LEVELS 3-8 1 2 3 4 5 6 11 LEVELS 1- ROOF + LEVEL FOUR 140'-0" 1 2 3 4 5 6 7 11 LEVELS 1- ROOF ◆ TO BRIDGE 114'-1" ◆ LEVEL TWO 113'-4" TYPICAL LEVEL 1 1 2 3 4 5 6 LEVELS 1-2 NORTH ELEVATION 1. FIELD VERIFY EXISTING DIMENSIONS PRIOR TO FABRICATION AND CONSTRUCTION. 2. COORDINATE WORK AREAS AND ACCESS WITH OWNER.

1 - FIX CURTAIN WALL LEAKS PN 22-175251) A01 2023-075M22 ACADEMIC (PROJECT F

MARTIN/MARTIN CONSULTING ENGINEERS

MAIN 303.431.6100 MARTINMARTIN.COM

REVISIONS NO. ISSUE DATE

PROJECT NO:

20.0814.S.04 © MARTIN/MARTIN 2020

08/27/2021

ELEVATIONS

SHEET NUMBER: S2.04

3. CONTRACTOR TO REPAIR RESULTING DAMAGE ASSOCIATED WITH REPAIRS INCLUDING LANDSCAPING, ADJACENT WALLS AND ROOF

